



(A) Final fluoroscopic image of a Medcomp Dignity CT port. The initials "CT" were printed in reverse with radiopaque ink at the base of the TIVAD chamber (arrow) to signify that it is compatible with power injection for contrast agents. (B) On post-implantation day 50, the attending nurse could not palpate the TIVAD septum for puncture. A subsequent control radiograph demonstrated the reversal of the initials "CT" in keeping with an inversion of the TIVAD chamber. It was explanted, and a new TIVAD was inserted on the contralateral side with fixation sutures.